

Classification 11.3111 **No.** 11722 **State** **Place**



Description.

24 inch plow. This plow was used for breaking the land for the first time in the lake bed of Lima Lake after drainage, 1930. It was drawn by a 60 H.P. tractor and would cut off stumps up to 4 and 6 inches in diameter.

Sutton. Sept. 1930.

